

METODO VOLT-AMPERMETRICO

METODO VOLT AMPERMETRICO

MISURA

$\alpha =$	51,90451	GRADI
$I_1 =$	1,056579	
PC=	81,06664	
PT=	84,74464	
QT=	108,0964	
Qcar	108,0889	


HELP

$\alpha =$	51,9045	GRADI
$I_1 =$	1,039671	
PC=	81,06872	
PT=	84,74469	
QT=	108,0964	
Qcar	108,0916	

AZIENDA

VALORI ATTESI

P	Qcar	S	I
81,12	108,16	135,2	1,04



RITORNA

STAMPA

ESEGUI

STOP

f =	50
R1 =	75
XL1 =	100
XC1 =	
E1 =	130
$\alpha c =$	53,13

VOLTMETRO A VALLE

	portata V	portata A	f sc	Rint bv	Rint ba	Lint bv	Lint ba	P persa	div lette	cos φ	VAL_MIS	KS
A		3	120		0,06		0,000014	0,06698	42,263		1,0566	0,025
V	150		150	4680				3,60874	129,96		129,96	1

CARATTERISTICHE DEGLI STRUMENTI

VOLTMETRO A MONTE

	portata V	portata A	f sc	Rint bv	Rint ba	Lint bv	Lint ba	P persa	div lette	cos φ	VAL_MIS	KS
A		3	120		0,06		0,000014	0,06485	41,587		1,0397	0,025
V	150		150	4680				3,61111	130		130	1